

ANDOORKONAM GRAMA PANCHAYATH

FITNESS CERTIFICATE

1. Name of Institution : BRIGHT CENTRAL SCHOOL KANIYAPURAM
2. Name of the Officer : ASST ENGINEER
3. Period for which the Certificate is issued : 2020-2021 AY
4. Classification of the building and Size (basis : multistoried Building
for classification) (See Annexure I) GF-18.50x 9.00 m
65.60 x 7.80 m
6.0 x 6.00 m
Permanent Single or Multistoried FF- 18.50x 9.00 m
6.0 x 6.00 m x 7 classrooms
5. Nature of defects if any
- a) Foundation and Basement
- b) Super structure
- c) Doors and windows NIL
- d) Wood work wrought put up
- e) Roof
- f) Flooring
- g) Miscellaneous
(Cracks etc)
6. Any Major defects noticed which will : NIL
render the building unsafe in any manner
7. Whether maintenance works have been : YES
done properly.
8. Whether the structure is sound or not : YES
For conducting classes

Note- 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc..

2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on18/06/2020..... And found to be fit to conduct classes for the period 2020-2021 AY.....For the reasons stated above.

Place KANIYAPURAM

Date 18/06/2020

Signature:

Designation:


Assistant Engineer
LSGD, Section
Andoorkonam Grama Panchayat

